

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending

Active

- L1: (1422) (296/216.01-224).CCLS.
- L2: (440) l1 and adjust\$
- L3: (192) l2 and height
- L4: (48) l1 and height with adjustment
- L5: (65) l3 and stop
- L6: (2) ("2629543").PN.
- L7: (235) plastic with roof with panel
- L8: (1) plastic with roof with panel with double with wall
- L9: (3) plastic with roof with panel with double
- L10: (14) plastic with roof with panel with inner
- L11: (37) plastic with roof with panel with inner

Failed

- (9260) 138/\$.ccls. and line\$

Saved

- (5) (("5545361") or ("5799991") or ("5988713") or ("6165588
- (7) ("5092512") or ("5124186") or ("5139297") or ("5219197
- (6) ("4165113") or ("4221413") or ("4320913") or ("4856833
- (5) ("5,092,512") or ("6,406,081") or ("5,799,991") or ("6
- (1148) ((293/15) or (293/102) or (293/120-121) or (293/154)
- (5) ("4,615,411") or ("4,347,277") or ("3,885,521") or ("5
- (4) ("4592886") or ("6592069") or ("4329879") or ("4403933
- (1) ("3934064").PN.

Search List Browse Queue Clear

DBs USPAT Plurals

Default operator: OR Highlight all hit terms initially

plastic with roof with panel
with inner

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (51)

UDC

Queue

Trash

| | Type | L # | Hits | Search Text | DBs | Time Stamp | Comment | Error |
|----|------|-----|------|--|--------------|----------------------|---------|-------|
| 1 | IS&R | L1 | 1422 | (296/216.01-224).CCLS | USPA T; U | 2004/10/0 5 13:17 | | |
| 2 | BRS | L2 | 440 | l1 and adjust\$ | USPA T | 2004/10/0 5 13:17 | | |
| 3 | BRS | L3 | 192 | l2 and height | USPA T | 2004/10/0 5 13:18 | | |
| 4 | BRS | L4 | 48 | l1 and height with adjustment | USPA T | 2004/10/0 5 13:18 | | |
| 5 | BRS | L5 | 65 | l3 and stop | USPA T | 2004/10/0 5 13:33 | | |
| 6 | IS&R | L6 | 2 | ("2629543").PN. | DERW ENT | 2004/10/0 5 13:37 | | |
| 7 | BRS | L7 | 235 | plastic with roof with panel | DERW ENT | 2004/10/0 5 13:37 | | |
| 8 | BRS | L8 | 1 | plastic with roof with panel with doubl | DERW ENT | 2004/10/0 5 13:38 | | |
| 9 | BRS | L9 | 3 | plastic with roof with panel with doubl | DERW ENT | 2004/10/0 5 13:38 | | |
| 10 | BRS | L10 | 14 | plastic with roof with panel with inner | DERW ENT | 2004/10/0 5 13:40 | | |
| 11 | BRS | L11 | 37 | plastic with roof with panel with inner | USPA T | 2004/10/0 5 13:40 | | |

NUM

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending

Active

- L1: (1422) (296/216.01-224).CCLS.
- L2: (440) 11 and adjust\$
- L3: (192) 12 and height
- L4: (48) 11 and height with adjustment
- L5: (65) 13 and stop
- L6: (2) ("2629543").PN.
- L7: (235) plastic with roof with panel
- L8: (1) plastic with roof with panel with double with wall
- L9: (3) plastic with roof with panel with double
- L10: (14) plastic with roof with panel with inner
- L11: (37) plastic with roof with panel with inner

Failed

- (9260) 138/\$.ccls. and line\$

Saved

- (5) (("5545361") or ("5799991") or ("5988713") or ("6165588
- (7) (("5092512") or ("5124186") or ("5139297") or ("5219197
- (6) (("4165113") or ("4221413") or ("4320913") or ("4856833
- (5) (("5,092,512") or ("6,406,081") or ("5,799,991") or ("6
- (1148) ((293/15) or (293/102) or (293/120-121) or (293/154)
- (5) (("4,615,411") or ("4,347,277") or ("3,885,521") or ("5
- (4) (("4592886") or ("6592069") or ("4329879") or ("4403933
- (1) ("3934064").PN.

Search List Browse Queue Clear

DBs USPAT Plurals

Default operator: OR Highlight all hit terms initially

plastic with roof with panel
with inner

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (51)

UDC

Queue

Trash

| | U | 1 | Document ID | Issue Dat | Page | Title | Current |
|----|--------------------------|-------------------------------------|------------------|-----------|------|---|---------|
| 39 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4715649 A | 19871229 | 5 | Locator and hold-down latch for removable veh | 296/218 |
| 40 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4467944 A | 19840828 | 6 | Storage apparatus for automobile.T top insert | 224/42. |
| 41 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4351560 A | 19820928 | 12 | Removable roof of a motor vehicle | 296/218 |
| 42 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4220368 A | 19800902 | 4 | Removable plastic roof panel | 296/215 |
| 43 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4205875 A | 19800603 | 6 | Roof vent window | 296/218 |
| 44 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3712665 A | 19730123 | 7 | LOCK FOR A REMOVABLE ROOF ATTACHMENT FOR VEH | 296/218 |
| 45 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3635518 A | 19720118 | 4 | MOUNTING OF A ROOF ATTACHMENT IN THE FRONT | 296/76 |
| 46 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6375249 B1 | 20020423 | 16 | Body structure of a mass transit vehicle | 296/178 |
| 47 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5041318 A | 19910820 | 16 | Composite structural member with integral lo | 428/57 |
| 48 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6039390 A | 20000321 | 48 | Chromogenic window assembly construction a | 296/211 |
| 49 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3815307 A | 19740611 | 4 | ROOF-TO-SIDEWALL UNIT METHOD JOINT STRUCTURE | 52/285. |
| 50 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 2489751 A | 19491129 | 6 | Roof or covering | 359/228 |
| 51 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 2230439 A | 19410204 | 4 | Automobile body structure | 296/211 |

NUM

EAST - [lined duct:2]

FileViewEditToolsWindowHelp

Pending

Active

Failed

Saved

L1: (217) (296/213).CCLS.

L2: (449) (296/208).CCLS.

L3: (99) 12 and (weatherstrip or seal)

L4: (103) 12 and roof

(9260) 138/\$.ccls. and line\$

(5) (("5545361") or ("5799991") or ("5988713") or ("6165588

(7) (("5092512") or ("5124186") or ("5139297") or ("5219197

(6) (("4165113") or ("4221413") or ("4320913") or ("4856833

(5) (("5,092,512") or ("6,406,081") or ("5,799,991") or ("6

(1148) ((293/15) or (293/102) or (293/120-121) or (293/154)

(5) (("4,615,411") or ("4,347,277") or ("3,885,521") or ("5

(4) (("4592886") or ("6592069") or ("4329879") or ("4403933

(1) ("3934064").PN.

(1) ("20008201").PN.

(1) ("2789043").PN.

(1) ("4615411").PN.

(3) (("10005718") or ("29916470")).PN.

(6) (plastic near2 metal with hybrid) and duct

(110) plastic near2 metal with hybrid

(1183) 138/\$.ccls. and liner

SearchListBrowseQueueClear

DBsUSPATPlurals

Default operator: ORHighlight all hit terms initially

12 and roof

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (82)

UDC

Queue

Trash

| | Type | L # | Hits | Search Text | DBs | Time Stam | Comment | Error I |
|---|------|-----|------|----------------------------------|--------------|----------------------|---------|---------|
| 1 | IS&R | L1 | 217 | (296/213).CCLS. | USPA T; U | 2004/10/0 8 06:22 | | |
| 2 | IS&R | L2 | 449 | (296/208).CCLS. | USPA T; U | 2004/10/0 8 06:22 | | |
| 3 | BRS | L3 | 99 | 12 and (weatherstrip or seal) | USPA T | 2004/10/0 8 06:24 | | |
| 4 | BRS | L4 | 103 | 12 and roof | USPA T | 2004/10/0 8 06:24 | | |

Ready

NUM

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending

Active

Failed

Saved

L1: (110) (296/220.01).CCLS.

L2: (94) (296/216.09).CCLS.

L3: (1) ("6672638").PN.

L4: (1) ("6419308").PN.

L5: (1) ("6485094").PN.

L6: (5) ("1162627").PN.

L7: (186) (292/dig.5).CCLS.

L8: (6) ("4351561" | "4415189" | "4801173" | "4917415" | "5

L9: (1) 5957511.URPN.

L10: (132) B60J007/11.ipc.

(5) (("5545361") or ("5799991") or ("5988713") or ("6165588

(7) (("5092512") or ("5124186") or ("5139297") or ("5219197

(6) (("4165113") or ("4221413") or ("4320913") or ("4856833

(5) (("5,092,512") or ("6,406,081") or ("5,799,991") or ("6

(1148) ((293/15) or (293/102) or (293/120-121) or (293/154)

(5) (("4,615,411") or ("4,347,277") or ("3,885,521") or ("5

(4) (("4592886") or ("6592069") or ("4329879") or ("4403933

(1) ("3934064").PN.

(1) ("20008201").PN.

Search

List

Browse

Queue

Clear

DBs

USPAT: DERWE

Plurals

Default operator:

OR

☒ Highlight all hit terms initially

B60J007/11.ipc.

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (80)

UDC

Queue


Trash

| | Type | L # | Hits | Search Text | DBs | Time Stam | Comment | Error |
|----|------|-----|------|-----------------------|------|-----------|---------|-------|
| 1 | IS&R | L1 | 110 | (296/220.01).CCLS. | USPA | 2004/10/0 | | |
| | | | | | T; U | 6 09:33 | | |
| 2 | IS&R | L2 | 94 | (296/216.09).CCLS. | USPA | 2004/10/0 | | |
| | | | | | T; U | 6 09:35 | | |
| 3 | IS&R | L3 | 1 | ("6672638").PN. | USPA | 2004/10/0 | | |
| | | | | | T; U | 6 09:36 | | |
| 4 | IS&R | L4 | 1 | ("6419308").PN. | USPA | 2004/10/0 | | |
| | | | | | T; U | 6 09:37 | | |
| 5 | IS&R | L5 | 1 | ("6485094").PN. | USPA | 2004/10/0 | | |
| | | | | | T; U | 6 09:41 | | |
| 6 | IS&R | L6 | 5 | ("1162627").PN. | DERW | 2004/10/0 | | |
| | | | | | ENT | 6 09:47 | | |
| 7 | IS&R | L7 | 186 | (292/dig.5).CCLS. | USPA | 2004/10/0 | | |
| | | | | | T; U | 6 09:55 | | |
| 8 | BRS | L8 | 6 | ("4351561" | USPA | 2004/10/0 | | |
| | | | | "4415189" "4801173" | T | 6 09:49 | | |
| 9 | BRS | L9 | 1 | 5957511.URPN. | USPA | 2004/10/0 | | |
| | | | | | T | 6 09:50 | | |
| 10 | BRS | L10 | 132 | B60J007/11.ipc. | USPA | 2004/10/0 | | |
| | | | | | T; D | 6 09:55 | | |

Hits

Details

HTML



⊖ Pending

 Active

L1: (110) (296/220.01).CCLS.

L2: (94) (296/216.09) .CCLS.

L3: (1) ("6672638").PN.

L4: (1) ("6419308").PN.

- L5: - (1) ("6485094").PN.

L6: (5) ("1162627").PN.

L7: (186) (292/diq.5).CCLS.

- L8: (6) ("4351561" | "4415189" | "4801173" | "4917415" | "5

L9: (1) 5957511.URPN.

L10: (132) B60J007/11.ipc.

Failed

9260) 138/\$.cc1s. and line\$

 Saved

- (5) ("5545361") or ("5799991") or ("5988713") or ("6165588

7) ("5092512") or ("5124186") or ("5139297") or ("5219197")

2 (6) ("4165113") or ("4221413") or ("4320913") or ("4856833

~~5~~ (5) ("5,092,512") or ("6,406,081") or ("5,799,991") or ("6

-2 (1148) ((293/15) or (293/102) or (293/120-121) or (293/154)


~~2~~ (5) ("4,615,411") or ("4,347,277") or ("3,885,521") or ("5

9 (4) ("4592886") or ("6592069") or ("4329879") or ("4403933

(1) ("3934064").PN.

(1) ("20008201").PN.

11-1107000-000-00

 Drafts

⌚ Pending

 Active

Failed

 Saved

 Favor

Tagged (8

UDC

 Question

Trash

| | U | 1 | Document ID | Issue Dat | Page | Title | Current |
|----|--------------------------|-------------------------------------|------------------|-----------|------|--|---------|
| 19 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4964440 A | 19901023 | 15 | Ribbed pipe | 138/122 |
| 20 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4780163 A | 19881025 | 7 | Method for lining pipeline | 156/94 |
| 21 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4272971 A | 19810616 | 10 | Reinforced tubular structure | 464/181 |
| 22 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3907049 A | 19750923 | 9 | Lined pipe and method of making same | 138/155 |
| 23 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6318795 B1 | 20011120 | 7 | Vibration preventing structure of tailgate i | 296/207 |
| 24 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6119306 A | 20000919 | 24 | Automotive deck lid bumper | 16/86A |
| 25 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6088878 A | 20000718 | 21 | Height adjustable automotive deck lid bum | 16/86A |
| 26 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6039388 A | 20000321 | 5 | Hood overslam bumper for automobiles | 296/207 |
| 27 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5482348 A | 19960109 | 6 | Vehicle hood support post member | 296/207 |
| 28 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6507976 B2 | 20030121 | 12 | Damper device | 16/82 |
| 29 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4653968 A | 19870331 | 8 | Adjustable abutment assembly | 411/247 |
| 30 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5735511 A | 19980407 | 8 | Self-adjusting stop means for cushioning | 267/140 |
| 31 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5950366 A | 19990914 | 10 | Seal structure for removable roof | 49/484 |
| 32 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5725272 | 19990310 | 9 | Vehicle roof assembly | 296/210 |

EAST - [lined duct:2]

FileViewEditToolsWindowHelp

Pending

Active

Failed

Saved

L1: (110) (296/220.01).CCLS.

L2: (94) (296/216.09).CCLS.

L3: (1) ("6672638").PN.

L4: (1) ("6419308").PN.

L5: (1) ("6485094").PN.

L6: (5) ("1162627").PN.

L7: (186) (292/dig.5).CCLS.

L8: (6) ("4351561" | "4415189" | "4801173" | "4917415" | "5

L9: (1) 5957511.URPN.

L10: (132) B60J007/11.ipc.

(9260) 138/\$.ccls. and line\$

(5) (("5545361") or ("5799991") or ("5988713") or ("6165588

(7) (("5092512") or ("5124186") or ("5139297") or ("5219197

(6) (("4165113") or ("4221413") or ("4320913") or ("4856833

(5) (("5,092,512") or ("6,406,081") or ("5,799,991") or ("6

(1148) ((293/15) or (293/102) or (293/120-121) or (293/154)

(5) (("4,615,411") or ("4,347,277") or ("3,885,521") or ("5

(4) (("4592886") or ("6592069") or ("4329879") or ("4403933

(1) ("3934064").PN.

(1) ("20008201").PN.

SearchListBrowseQueueClear

DBsUSPAT: DERWEPlurals

Default operator: ORHighlight all hit terms initially

B60J007/11.ipc.

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (80)

UDC

Queue

Trash

| | U | 1 | Document ID | Issue Dat | Page | Title | Current |
|----|--------------------------|-------------------------------------|-----------------|-----------|------|--|---------|
| 32 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5725273 A | 19980310 | 8 | Vehicle roof assembly with removable and stor | 296/218 |
| 33 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5513891 A | 19960507 | 22 | Removable roof accommodating structure | 296/37. |
| 34 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5193874 A | 19930316 | 10 | T-top insert storage rack with locking mecha | 296/37. |
| 35 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5080428 A | 19920114 | 8 | Foldable roof assembly for vehicles having a T | 296/218 |
| 36 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4784431 A | 19881115 | 11 | Automobile roof structure | 296/218 |
| 37 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4718710 A | 19880112 | 17 | Unit for storing demountable roof panel | 296/37. |
| 38 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4717192 A | 19880105 | 19 | Unit for storing demountable roof panel | 296/37. |
| 39 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4715649 A | 19871229 | 5 | Locator and hold-down latch for removable veh | 296/218 |
| 40 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4467944 A | 19840828 | 6 | Storage apparatus for automobile T top insert | 224/42. |
| 41 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4351560 A | 19820928 | 12 | Removable roof of a motor vehicle | 296/218 |
| 42 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4220368 A | 19800902 | 4 | Removable plastic roof panel | 296/215 |
| 43 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4205875 A | 19800603 | 6 | Roof vent window | 296/218 |
| 44 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3712665 A | 19730123 | 7 | LOCK FOR A REMOVABLE ROOF ATTACHMENT FOR VEH | 296/218 |
| 45 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3625510 A | 19720110 | 4 | MOUNTING OF A ROOF | 296/37. |

HB

Details

HTML

NUM

Ready

EAST - [lined duct:2]

FileViewEditToolsWindowHelp

Pending

Active

Failed

Saved

L1: (110) (296/220.01).CCLS.

L2: (94) (296/216.09).CCLS.

L3: (1) ("6672638").PN.

L4: (1) ("6419308").PN.

L5: (1) ("6485094").PN.

L6: (5) ("1162627").PN.

L7: (186) (292/dig.5).CCLS.

L8: (6) ("4351561" | "4415189" | "4801173" | "4917415" | "5

L9: (1) 5957511.URPN.

L10: (132) B60J007/11.ipc.

(9260) 138/\$.ccls. and line\$

(5) (("5545361") or ("5799991") or ("5988713") or ("6165588

(7) (("5092512") or ("5124186") or ("5139297") or ("5219197

(6) (("4165113") or ("4221413") or ("4320913") or ("4856833

(5) (("5,092,512") or ("6,406,081") or ("5,799,991") or ("6

(1148) ((293/15) or (293/102) or (293/120-121) or (293/154)

(5) (("4,615,411") or ("4,347,277") or ("3,885,521") or ("5

(4) (("4592886") or ("6592069") or ("4329879") or ("4403933

(1) ("3934064").PN.

(1) ("20008201").PN.

SearchListBrowseQueueClear

DBsUSPAT: DERWEPlurals

Default operator: ORHighlight all hit terms initially

B60J007/11.ipc.

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (80)

UDC

Queue

Trash

| | U | 1 | Document ID | Issue Dat | Page | Title | Current |
|----|--------------------------|-------------------------------------|-------------|-----------|------|--------------------------|---------|
| 44 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3712665 | 19730123 | 7 | LOCK FOR A REMOVABLE | 296/218 |
| | | | A | | | ROOF ATTACHMENT FOR VEH | |
| 45 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3635518 | 19720118 | 4 | MOUNTING OF A ROOF | 296/76 |
| | | | A | | | ATTACHMENT IN THE FRONT | |
| 46 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6375249 | 20020423 | 16 | Body structure of a | 296/178 |
| | | | B1 | | | mass transit vehicle | |
| 47 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5041318 | 19910820 | 16 | Composite structural | 428/57 |
| | | | A | | | member with integral lo | |
| 48 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6039390 | 20000321 | 48 | Chromogenic window | 296/211 |
| | | | A | | | assembly construction a | |
| 49 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3815307 | 19740611 | 4 | ROOF-TO-SIDEWALL UNIT | 52/285. |
| | | | A | | | METHOD JOINT STRUCTURE | |
| 50 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 2489751 | 19491129 | 6 | Roof or covering | 359/228 |
| | | | A | | | | |
| 51 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 2230439 | 19410204 | 4 | Automobile body | 296/211 |
| | | | A | | | structure | |
| 52 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5205607 | 19930427 | 8 | Automobile with | 296/201 |
| | | | A | | | removeable roof | |
| 53 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US RE32496 | 19870908 | 8 | Removable roof panels | 296/218 |
| | | | E | | | for vehicles | |
| 54 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4830426 | 19890516 | 10 | Latching arrangement | 296/121 |
| | | | A | | | for a top at the windsh | |
| 55 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3476437 | 19691104 | 7 | TOP FOR MOTOR | 296/218 |
| | | | A | | | VEHICLES. ESPECIALLY FOR | |
| 56 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6309007 | 20011030 | 16 | Two-piece hardtop for a | 296/103 |
| | | | B1 | | | sport utility vehicle | |
| | | | | | | | |

HibDetailsHTML

Ready

NUM

EAST - [lined duct:2]

FileViewEditToolsWindowHelp

Pending

Active

Failed

Saved

L1: (110) (296/220.01).CCLS.

L2: (94) (296/216.09).CCLS.

L3: (1) ("6672638").PN.

L4: (1) ("6419308").PN.

L5: (1) ("6485094").PN.

L6: (5) ("1162627").PN.

L7: (186) (292/dig.5).CCLS.

L8: (6) ("4351561" | "4415189" | "4801173" | "4917415" | "5

L9: (1) 5957511.URPN.

L10: (132) B60J007/11.ipc.

(9260) 138/\$.ccls. and line\$

(5) (("5545361") or ("5799991") or ("5988713") or ("6165588

(7) (("5092512") or ("5124186") or ("5139297") or ("5219197

(6) (("4165113") or ("4221413") or ("4320913") or ("4856833

(5) (("5,092,512") or ("6,406,081") or ("5,799,991") or ("6

(1148) ((293/15) or (293/102) or (293/120-121) or (293/154)

(5) (("4,615,411") or ("4,347,277") or ("3,885,521") or ("5

(4) (("4592886") or ("6592069") or ("4329879") or ("4403933

(1) ("3934064").PN.

(1) ("20008201").PN.

SearchListBrowseQueueClear

DBsUSPAT: DERWEPlurals

Default operator: ORHighlight all hit terms initially

B60J007/11.ipc.

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (80)

UDC

Queue

Trash

| | U | 1 | Document ID | Issue Dat | Page | Title | Current |
|----|--------------------------|-------------------------------------|-------------|-----------|------|---|---------|
| 56 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6309007 | 20011030 | 16 | Two-piece hardtop for a sport utility vehicle | 296/103 |
| 57 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6062637 | 20000516 | 16 | Sunroof for motor vehicles | 296/216 |
| 58 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6059356 | 20000509 | 7 | Two part roof arrangement | 296/218 |
| 59 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 6039391 | 20000321 | 9 | Hatch roof attaching construction for a T-ba | 296/218 |
| 60 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5052743 | 19911001 | 9 | Open-top type vehicle roof structure | 296/210 |
| 61 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5037146 | 19910806 | 5 | Lock for a detachable vehicle body part...pref | 292/202 |
| 62 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4917415 | 19900417 | 10 | Latching mechanism for a top of a vehicle...esp | 292/113 |
| 63 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4898410 | 19900206 | 10 | Latching arrangement for a top | 292/241 |
| 64 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4133576 | 19790109 | 6 | Hatch for vehicle roofs | 296/218 |
| 65 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 4131970 | 19790102 | 9 | Quick-release-hinge device | 16/270 |
| 66 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 3603636 | 19710907 | 8 | MOUNTING ARRANGEMENT FOR A VEHICLE BODY ROOF | 296/218 |
| 67 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 2392874 | 19460115 | 5 | TEXT NOT AVAILABLE | 292/36 |
| 68 | <input type="checkbox"/> | <input checked="" type="checkbox"/> | US 5042869 | 19910827 | 12 | Locking arrangement for a motor vehicle top | 296/121 |

HitsDetailsHTML

Ready

NUM

